

REV: OCT 4, 2021									
Power Station	Unit	Capacity (MW)	Available Capacity	Condition	Person in charge of attending findings	NME (Million)	Currents Status/ Action Plan / Comments		
PREPA's Base Generation									
	CT 5	160	150	Available		\$40	Major overhaul; Proposed dates: November 15, 2021; Alternative: January 15, 2022; taking moderate risks. Approximate cost \$40 million including LTSA (Long Term Services Agreement).		
	STM 5	60	51	Available			Major overhaul; Proposed dates: November 15, 2021; Alternative: January 15, 2022. Verifying delivery of steam turbine parts is a critical path.		
	CT 6	160	150	Available		\$30	Major overhaul; Proposed date: February 2023; Approximate cost \$30 million.		
	STM 6	60	49	Available			Major overhaul; Proposed date: February 2023.		
San Juan	7	100	0	Not available	Eng. Alejandro Castillo / Plant Manager	\$5	Unit with low vacuum problems due to the crossover joint; Return to service on September 30, 2021. It goes out of service on October 2 to correct vacuum problems and boiler inspections; must return to service on October 8, 2021. Turbine rotors have expired hours for major repair (over 70K hours). Approximate repair cost \$5 millions. Major inspection date to be determined. Unit in limited use (8%) according to EPA MATS (Mercury and Air Toxic Standards).		
	8	100		Not available			\$10	Boiler pipe breakage problems, steam leaks and feedwater heater #6 problems. Limited use unit (8%) according to EPA (MATS). Boiler air leaks. Approximate cost of boiler repairs and auxiliary equipment, \$10 million including new boiler piping.	
	9	100	96	Available			DEMI (Demineralized) water production problems. Temporary water production plant of the Central (RO) faces operational problems. In the process of completing the installation of a new permanent DEMI plant.		
	10	100		Not available		\$15	Low pressure turbine fault. Unit not available since the end of 2015. Returning the unit to service entails an approximate investment of \$15 million and an estimated duration of the works, 6 months.		
	1	85		Not available	Eng. Antonio Kalil / Plant Manager	\$10	Limited use unit EPA (MATS). Boiler air leaks, requires replacement of boiler piping. Generator has major stator failure and requires turbine work.		
	2	85		Not available		\$15	Limited used unit EPA (MATS). Faulty unit generator; The unit's Main Power Transformer is used as an output transformer for new MPA FT-8.		
Palo Seco	3	216	216	Available		\$5	Major repair completed June 2021. Unit returned to service on October 2, 2021, after forced departure due to boiler failure. It is required to purchase boiler tube and economizer panels for approximately \$5 million, for fiscal year 2022-2023.		
	4	216	0	Not available		\$2	Forced outage due to oil leak through control wiring. High pressure differential on the air preheaters. Unit expected to return to service on Sunday, October 10, 2021. Environmental outage rescheduled for January 2022, after Costa Sur 6 return to service. Work will be carried out on the boiler and replacement of the air pre-heater baskets.		
Aguirre Steam Plant	1	450	375	Available	Eng. Alexis Cruz / Plant Manager	\$18	Boiler air in leakages. Major repair rescheduled for January 2022, after the entry of Costa Sur 6. Major works, environmental outages, boiler work and replacement of turbine rotors for an approximate \$18 millions.		
	2	450	121	Available		\$0.35	Feed water control valve issues. In addition, it is necessary to correct boiler air in leakages and air preheaters cleaning. It is recommended to shutdown the unit for five days to address problems with the feed water system. This action eliminated actual limitation. Unit outage is scheduled once Costa Sur 5 returns to service.		



REV: OCT 4, 2021

Power Station	Unit	Capacity (MW)	Available Capacity	Condition	Person in charge of attending findings	NME (Million)	Currents Status/ Action Plan / Comments
	5	410	0	Not available	Eng Miguel Beauchama	\$15	Main steam piping failure on September 13, 2021. Unit expected to return service on Wednesday, October 6, 2021. Major outage (boiler, environmental maintenance and replacement of turbine rotors) scheduled for October 2022. Approximate cost \$15 million.
South Coast	6	410	0	Not available	- Eng. Miguel Beauchamp/ Plant Manager	\$5	Low pressure turbine failure (LP turbine failure) after major unit repair including these rotors for \$20 million. Rotors were shipped to the US workshop by ship during the week of September 20-27. Findings report is expected for October 18, 2021. Unit expected delivery unit January 15, 2022 at an approximate cost of replacement of damaged parts of \$5 million.
Total PREPA Base Generation		3162	1208	38.20%		\$170.35	Available



REV: OCT 4, 202

REV: UCI 4, 2021										
Power Station	Unit	Capacity (MW)	Available Capacity	Condition	Person in charge of attending findings	NME (Million)	Currents Status/ Action Plan / Comments			
	PREPA's Reserve Generation Fleet									
	I-1	50	48	Available CC	Eng. Harry Velázquez / Plant Manager	\$1	Hot gas path inspection \$1M, April 2022.			
	I-2	50	48	Available SC		\$1	Inlet filters Clogged. Hot gas path inspection scheduled for June 2022.			
	I-3	50	48	Available		\$2.5	Major inpection scheduled for January 2022. \$2.5M			
	I-4	50	45	Available						
Aguirre Combined	ST-1	96	38	Available			Condenser fouling and air in leakages. Available with HRSG 1-1 & 1-3.			
Cycle	II-1	50		Not available			MPT 2-1, 2-2 failure.			
	II-2	50		Not available			MPT 2-1, 2-2 failure. Start up tests.			
	II-3	50	50	Available						
	II-4	50		Not available		\$1.7	Stand by Transformer fail. Hot gas path inspection and spare rotor \$1.7M.			
	ST-2	96		Not available			MPT 2-1, 2-2 failure. Start up tests.			
Total Aguirre	CC	592	277	46.79%		\$6.2	Availability			
DAGUAO	1-1	21	18	Available						
DAGUAU	1-2	21	19	Available	- Eng. José Vázquez HG Head Division / - Eng. José Pagán Operation Manager					
AGUIRRE	2-1	21		Not available		\$8	Unit requires major turbine repair and a complete generator assembly. Estimate \$8 million.			
AGUINNE	2-2	21	21	Available						
	1-1	21	18	Available						
	1-2	21		Not available		\$0.3	Generator breaker failure.			
	2-1	21	21	Available						
PALO SECO	MPA 1	23		Not available		\$0.1	Environmental air permit. Contract awarded to perform environmental acceptance tests. Waiting for EPA approval of emission testing.			
	MPA 2	23		Not available		\$0.1	Environmental air permit. Contract awarded to perform environmental acceptance tests. Waiting for EPA approval of emission testing.			
	MPA 3	23		Not available		\$0.1	Environmental air permit. Contract awarded to perform environmental acceptance tests. Waiting for EPA approval of emission testing.			
COCTA CLID	1-1	21		Not available			Unit reached full speed not load with excitation. Phasing tests schedule for October 17.			
COSTA SUR	1-2	21		Not available		\$2	Turbocompressor replacement.			
JOBOS	1-1	21	20	Available						
	1-2	21	20	Available			Due for major inspection (August 2020) and speed reduction gearbox replacement.			
YABUCOA	1-1	21		Not available			Alignment process. Startup testing scheduled for October 8.			
	1-2	21		Not available			Alignment process. Startup testing scheduled for October 22.			
VEGA BAJA	1-1	21		Not available		\$0.10	Voltage regulator repair unit expected in service on October 15, 2021			
	1-2	21		Not available		\$2	Turbocompressor major failure.			
Total 18 Peaking	384	137	35.68%		\$12.7	Availability				



REV: OCT 4, 2021

Power Station	Unit	Capacity (MW)	Available Capacity	Condition	Person in charge of attending findings	NME (Million)	Currents Status/ Action Plan / Comments
	1A	27.5		Not available	- Eng. José Vázquez / - Eng. Waldo Córdoba - Plant Manager	\$17	Gas generator and power turbine (1B) in critical condition. Repair Cost estimate \$17 million for both units
	1B	27.5		Not available		717	1A an 1B.
	2A	27.5	27.5	Available			
	2B	27.5	27.5	Available			
MAYAGÜEZ	3A	27.5	25.5	Available			
	3B	27.5	25.5	Available			
	4A	27.5		Not available		\$0.8	Combustor casing crack failure. First stage nozzle issues. Pending proposal evaluation. Repair cost Estimate \$800K.
	4B	27.5	25	Available			
Total Mayagi	Total Mayagüez		131			\$17.8	
	1	82.5		Not available	Eng. Herminio Arroyo / Plant Manager	\$18	Unit out of service since 2011; Combustion turbine failure; Proposal \$18 million and six months.
CAMBALACHE	2	82.5	77	Available			
	3	82.5	77	Available			
Total Cambala	Total Cambalache		154			\$18	
VIEQUES	1	3	3	Available	Eng. José Vázquez /		
VIEQUES	2	3	0	Not available			Troubleshooting control system issues.
	1	2	2	Available	Eng. Waldo Córdoba		
Culebra	2	2	2	Available	Plant Manager		
	3	2	2	Available			
Total Vieques and Culebra		12	9				
Total Peaking & Emergency Units		1,455.5	708.0	48.64%		\$55	Availability



REV: OCT 4, 202

NEV. OCT 4, 2021										
Power Station	Unit	Capacity (MW)	Available Capacity	Condition	Person in charge of attending findings	NME (Million)	Currents Status/ Action Plan / Comments			
HYDROELECTRICS										
Toro Negro	1-1	1.5	1.5	Available						
Toro Negro	1-2	1.5	1.5	Available						
Toro Negro	1-3	1.5	1.5	Available						
Toro Negro	1-4	4.5	4.5	Available						
Toro Negro	2	2		Not Available			Turbine inlet main valve replacement. Phasing test pending.			
Yauco	1	25		Not Available		\$8	Pending turbine and generator major overhaul. Federal restoration funding allocation for \$8M.			
Yauco	2-1	4.5	2	Available			Limited pending relay protection system modifications.			
Yauco	2-2	4.5	4.3	Available						
Garzas	1-1	3.6	4	Available	Eng. José Vázquez / Head Division					
Garzas	1-2	3.6		Not Available			Generator bearing repair. Expected in-service on October 2021.			
Garzas	2	5		Not Available			Transmission line failure due to Hurricane Maria. Federal restoration funding approved.			
Caonillas	1-1	9		Not Available		\$5	Station flooding failure due to Hurricane Maria. In preparation of specifications and bid process			
Caonillas	1-2	9		Not Available		ې کې	documents. Federal restoration funding allocation for \$5M.			
Caonillas	2	3.6		Not Available			Pending major restoration budget approvals.			
Dos Bocas	1	5		Not Available			Restored generator in coordination for transportation to site.			
Dos Bocas	2	5	5	Available						
Dos Bocas	3	5	5	Available						
Patillas	1-1	0.8		Not Available			Downstream flow risk concerns.			
Patillas	1-2	0.6		Not Available			Downstream flow risk concerns.			
Río Blanco	1	2.5		Not Available			Penstock major failure. Federal restoration funding approved.			
Río Blanco	2	2.5		Not Available			Penstock major failure. Federal restoration funding approved.			
Total Hydro)	100.2	29.3	29.24%		\$13				

NME (necessary maintenance expenses)